


Sundström



SR 700

SYSTEM OVERVIEW



No.	Description	Name	Art No.
1.	Fan unit	SR 700	R06-0721
2.	Filter adapter	SR 711	R06-0701
3.	Particulate filter P100/HE, SR 510	SR 510	H02-1321
4.	Particulate filter HE, SR 710	SR 710	H02-1521
5.	Pre-filter holder		R01-0605
6.	Battery HD 3.5 Ah	SR 702	T06-0701
7.	Battery charger		R06-0437
8.	Helmet with visor	SR 580	H06-8021
9.	Full face mask, PC visor	SR 200	H01-1221
	Full face mask, glass visor	SR 200	H01-1321
10.	Breathing hose 0,9 m PU	SR 550	T01-1216
	Breathing hose 0,7 m rubber	SR 551	T01-1218
11.	Harness	SR 552	T06-0116
12.	Belt cotton	SR 508	R06-0101
13.	Belt leather	SR 503	T06-0103
	Belt leather, large	SR 503	T06-0107
14.	Belt rubber	SR 504	T06-0104
15.	Belt PVC		T06-0124
16.	Flow meter	SR 356	R03-0346

